DPM2091

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration Form Approved OMB No. 44 R1387

P/N 28-AD-0019

		0503	10011			
MANUFACTURER'S NAME		SECT	ION I			
	+ D.	C	· • • • • • • • • • • • • • • • • • • •	TELEPHONE N	Ο.	
Ssex Chemical Corp. Coas	odel			30-083I		
19451 Susana Road, Compt			70000 000 000 0000	000000		
dhesive, MYLAR W/Accelerator	PRO-	SEAL 5		UIN Y MIS		
N/A		·	FORMULA N/A			
SECTION	V 11 -	HAZAI	RDOUS INGREDIENTS		·	
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC CO.	ATINGS	%	TLV (Units)
PIGMENTS			BASE METAL	ì		
CATALYST			ALLOYS			
VEHICLE POLYSULFICE resins	80	-90%	METALLIC COATINGS			
solventsKetone	1	-2%	FILLER METAL PLUS COATING OR CORE FLUX			
ADDITIVES Filler	5	-10%	OTHERS	1		
OTHERS		_			Ţ	
AUTXIM SUOCRASAH	S OF C	THER LI	DUIDS, SOLIDS, OR GASES		%	TLV (Units)
						1011/13
					\dashv	
						
		 -			- i	
		•				
SEC	CTION	V HI - F	PHYSICAL DATA	· · · · · · · · · · · · · · · · · · ·		
BOILING POINT (°F.)	1	N/A	SPECIFIC GRAVITY (H2O=1)		1.3	
/APOR PRESSURE (mm Hg.)]]	N/A	PERCENT, VOLATILE BY VOLUME (%)		2%	
APOR DENSITY (AIR=1)	. 1	N/A	EVAPORATION RATE		N/A	
SOLUBILITY IN WATER	I	Nil				
APPEARANCE AND ODOR Amber past	e -	merca	aptan odor.			
SECTION IV	FIRI	E AND E	EXPLOSION HAZARD DATA			
Cyer 200 deg. F ope	n Ci	 1D	FLAMMABLE LIMITS N/A	Lei		Uei
EXTINGUISHING MEDIA				<u> </u>		
Dry chemical, carbon procedures		obe, oxide'	LOAM, Water spray			
· · · · · · · · · · · · · · · · · · ·						

	SECTION V - HEALTH HAZARD DATA	
THRESHOLD LIMIT VALUE	LD ₅₀ single dose oral rats 0.5 to 5g per kg	
EFFECTS OF OVEREXPOSUR	May cause irritation of skin or mucos membranes.	
EMERGENCY AND FIRST ALE	PROCEDURES Flush thoroughly with water, use soap on	
skin. If accid	dently ingested, give emetic, consult physician.	

	•	,	SECTIO	ON VI - REACTIVITY DATA				
STABILITY	UNSTÀB	LE		CONDITIONS TO AVOID				
· 	STABLE		х					
INCOMPATABIL		<u> </u>		id strong oxidizing agents.				
HAZARDOUS D	ECOMPOSITIO	N PRODUC	TS SO	2, .CO ₂ , H ₂ O, upon combusion				
HAZARDOUS		AY OCCUR		CONDITIONS TO AVOID				
POLYMERIZATI		WILL NOT OCCUR .		x				
	•	*						

· · SECTION VII - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	
Clean up spillage with rags and/or sweeping compoun	d and
solvents	
WASTE DISPOSAL METHOD	
Preferably burn waste.	

	SECTION VIII - SPECIAL	PROTECTION IN	FORMATION	
RESPIRATORY PI	ROTECTION (Specify type) In confin	ned areas. (Cannister type	
VENTILATION			SPECIAL	<u></u>
MECHANICAL (General)			OTHER	
PROTECTIVE GLOVES Recommended		EYE PROTECTION Recommended		
OTHER PROTECT	IVE EQUIPMENT Coveralls	or aprons	,	

SECTION IX - SPECIAL PRECAUTIONS						
PRECAUTIONS TO BE TAKEN IN HANDLING AND S Avoid contact, do not inge	st. Stor	e in	closed	container	below	
80 deg. F				· · · · · · · · · · · · · · · · · · ·	,	 :
OTHER PRECAUTIONS - None	: • • ·					

PAGE (2)

GPO 934-110

Form OSHA-20 Rev. May 72